




NO
DOUBTS

SPART



TOASTER RACK

WL5002



NO
DOUBTS

ASSEMBLY INSTRUCTION

I . Notice of assembly

- * An enough dimension will be required to assemble and properly use the machine.
- * Please use floor padding, such as cardboard, to avoid scratching your floor during assembly.
- * The nuts and bolts have a little grease on them to protect them from corrosion. Please keep a rag handy to wipe your hands.
- * All plastic end caps and plugs have been assembled on the unit prior to shipment. They are shown on the assembly drawings for reference in the event replacement parts are needed.
- * The machine uses several different lengths of bolts. Be careful to use the correct length of bolt called for at each step of assembly.
- * Do not touch the wires and cables attention when drilling.

II . Before you begin


Locate a comfortable work site. Assemble your machine in an open space with ventilation and lighting, and with the help of other person. The machine posses a large area, so you do not place it in living room.

Find your tools. You will need the following tools to assemble your machine.

- . Standard screwdriver
- . WD40 lubricant or Vaseline (if necessary)

III . Assembling your machine

EXPLODED DRAWING



| NUMBER | DESCRIPTION | QUANTITY |
|--------|-------------|----------|
| 1 | RACK | 1 |
| 2 | HANDLE CAP | 1 |
| 3 | SQUARE PLUG | 1 |
| 4 | WHEEL | 2 |
| 5 | BOLT M8*45 | 2 |
| 6 | WASHER 8 | 4 |
| 7 | LOCK NUT M8 | 2 |

www.zunfit.com



ITALY OFFICE

Zun Srl
via Mammarella snc
66100 Chieti Scalo (CH), Italy
Email: info@zunfit.com
Phone: +39 0871 551762

CHINA OFFICE

Zunone
83# South Tongfu Road,
Nantong Jiangsu China
Email: simon@zunone.cn
Phone: +0086-13901602295